



## **Addendum**

Upon inspection of unit H-Lower at Sirenusa we discovered many subterranean shelter tubes both on the interior and exterior of the structure.

- 1) Entrance to unit and exterior perimeter- To the right of the entrance a single shelter tube was present. The perimeter has about 10 old shelter tubes which are crumbling and falling off structure. No visible active subterranean termites are present.
- 2) Office- Remnants of a single shelter tube was discovered on the west side wall. No visible termite activity was present.
- 3) Living room- Remnants of shelter tubes were found behind couch and in the cove molding along ceiling. The shelter tubes behind couch and in the cove molding were dry and crumbling. No visible termite activity was present

The owner's closet was inspected and has evidence of active Powder post beetles. Treatment is needed to eradicate these pests. The only way to treat for powder post beetles is fumigation.

As indicated no treatment is necessary for subterranean termites.

All inspections were completed in the presence of Felix Collazo.